
azard lert ive omorrow



SAFETY KEYPOINTS:

- Stay out of pinch point and "Red Zone" areas.
- Communicate your intended movements with equipment operators and wait for acknowledgment before
- Ensure proper task training is conducted on equipment operators (including production observations).
- Report all near miss accidents to your supervisors; this helps identify hazards and implement preventative measures.

Remember to ask yourself:

Am I in a safe place? Where is my co-worker?

Does my co-worker know where I am?

It's up to each miner and their supervisors to help develop a strong safety culture!

